UNCONTROLLED DOCUMENT

REV.

E.C.N. NUMBER AND REVISION COMMENTS

_PB-S01115151S

PART NUMBER

REV. \Box


➣


#11290. #11148.


E.C.N. E.C.N.


01.24.07 12.8.05


DATE














PCB LAYOUT

NOTES:

MILKY WHITE DIFFUSED WINDOW.
 RECOMMEND SML-LX2832 SERIES LED.

MAX.= +0.00 -DECIMAL

_PB-S01115151S PART NUMBER

15mm SQUARE LIGHT BAR.

REV. \Box

CONFIDENTIAL INFORMATION

THE INFORMATION CONVIDENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

*UNILESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), X.X=±0.5 (±0.020), X.XX=±0.25 (±0.010), X.XXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MIN= +DECIMAL PRECISION

RELIABILITY NOTE
OUR MANY YEARS OF EXPERIENCE DITA ACCUMULATION INDICATE THAT
SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.
PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

DRAWN BY: CHECKED BY: 5 APPROVED BY: 6

290 E. HELEN ROAD PALATINE, IL 60067–6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw DATE:

.12.02 유 1

≥