# **INFORMATION NOTE**



N° 020/19

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Update of user manual affecting TLE984x family

Infineon Technologies AG
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0
Chairman of the Supervisory Board: Dr. Eckart Sünner
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck
Registered Office: Neubiberg Commercial Register
Amtsgericht München HRB 126492

2019-04-02 Page 1 of 2

## **INFORMATION NOTE**



#### N° 020/19

### Update of user manual affecting TLE984x family

Products affected: Please refer to attached affected product list 1\_cip02019

**▶** Detailed Change Information:

**Subject:** Update of user manual affecting TLE984x family

**Reason:** improved description and correction of errors

Description: Old New 1.0 1.1 user manual revision

**▶** Product Identification: not applicable

update of user manual only ► Impact of Change:

▶ Attachments: affected product list 1\_cip02019

user manual revision 1.1 is published within section documents and user

manuals on the webpage http://www.infineon.com/TLE984x

Intended start of delivery:

not applicable

If you have any questions, please do not hesitate to contact your local Sales office.

2019-04-02 Page 2 of 2

#### Information Note N° 020/19

Update of user manual affecting TLE984x family



Sales name	SP number	OPN	Package
TLE9842-2QX	SP001285608	TLE98422QXXUMA1	PG-VQFN-48
TLE9842QX	SP001117838	TLE9842QXXUMA1	PG-VQFN-48
TLE9843-2QX	SP001285610	TLE98432QXXUMA1	PG-VQFN-48
TLE9843QX	SP001117840	TLE9843QXXUMA1	PG-VQFN-48
TLE9844-2QX	SP001285612	TLE98442QXXUMA1	PG-VQFN-48
TLE9844QX	SP001117842	TLE9844QXXUMA1	PG-VQFN-48
TLE9845QX	SP001185098	TLE9845QXXUMA1	PG-VQFN-48