




HOME > PRODUCTS > ANALOG > SOCKETMODEM® > MT5692SMI-X-L-92.R1

# SocketModem®

## MT5692SMI-X-L-92.R1

94453131LF

V.92 Serial Data/V.17 Fax w/o LED Pins, 3.3V - Single or 50-Pack



### MANUALS & GUIDES

SocketModem® MT5692SMI Device Guide	Developer Guide	Version A	● DOWNLOAD
Universal Socket MT-SMI-DK Developers Guide	Developer Guide	Version U	● DOWNLOAD
+V Voice Command Developer's Guide	Developer Guide	Version Rev. E	● DOWNLOAD
AT Commands for 5692 Products	Reference Guide	Version E	● DOWNLOAD

### SOFTWARE, FIRMWARE & DRIVERS

Firmware	Resolution firmware patch for MT5692SMI, 1.01K. Upgrade will require the AT** flash method.	1.01K	● DOWNLOAD
<p>Noted in Resolution 5031075: RING detect from German analog phone line</p> <p>This version of firmware remains available for the following issue:</p> <p>Using the MT5692SMI (.R1) product with 1.01L code, it is noticed in certain conditions/circumstances where the RING is no longer being detected, whereas it was previously being detected with the 1.01J version of code. Issue initially noticed on standard German analog phone lines, however, could apply to numerous variances of line conditions.</p> <p>To apply the Resolution:</p> <p>Flash modem with 1.01K code.</p> <p><b>Product(s) affected: MT5692SMI,MT5692SMI-P,MT5692SMI-V</b></p>			
Firmware	Latest firmware patch for MT5692SMI, 1.01L. Upgrade will require the AT** flash method.	1.01L	● DOWNLOAD



#### GET CONNECTED



#### STAY CONNECTED

Subscribe to receive the latest MultiTech news and learn more about how to create, connect, and communicate.

Enter your email

SUBSCRIBE

#### PRODUCTS

Wireless  
Analog  
Embedded  
External  
FaxFinder & VOIP  
Developer Tools  
Accessories  
DeviceHQ™  
Services  
Product Brochure

#### APPLICATIONS

Transportation  
Energy  
Retail  
Healthcare  
Remote Monitoring

#### COMPANY

Contact  
Support  
Careers  
How to Buy  
News  
Events  
Scholarship  
Feedback

#### LEGAL

Terms of Service  
Standard Terms and Conditions of Sale  
Privacy Policy  
Standard Warranty  
Security Statement  
Shipping Policy  
Return Policy