

Harwin plc Fitzherbert Road Farlington, Portsmouth Hampshire PO6 1RT United Kingdom

Reception: +44 (0)23 9231 4545 Sales Desk: +44 (0)23 9237 0451 Fax: +44 (0)23 9231 4590

Thursday 14<sup>th</sup> June, 2012

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following products are now obsolete with immediate effect. Some existing stock is available, and will be available until stocks are exhausted. Please contact <a href="mailto:quote@harwin.co.uk">quote@harwin.co.uk</a> if you wish to purchase any of the existing stock.

- M20-610xx05
- M20-611xx05
- M402F1-xx05R
- M402F2-xx05R
- M402M1-xx05R
- M402M2-xx05R
- S1901-xx, S1901-xxR

Please see the attached spreadsheet for a complete list of affected part numbers, as well as replacement product where applicable. Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team technical@harwin.com